

## Sets, Kits, and Outfits, Components List Tool Kit, Small Arms Repairman

SC: 5180-95-A07  
NSN: 5180-00-357-7770, 5180-01-500-4790  
LIN: W51910

### System Description

MOS: 45B/92Y The SARK consists of 64 tools including the following: Screwdrivers, sharpening stones, files, pliers, block bench, vise and vise caps, tweezers, small parts box, drive punches, hex key wrenches, hammers, 6" rule, tape measure, cold chisels, drift brass. The entire tool load is contained in a 6-drawer injection molded plastic tool box. Each drawer has a foam liner with individual cutouts that hold each tool in a specific place.

### System Mission

The modernized Small Arms Repairman Tool Kit (SARK) provides the necessary components to repair and maintain small arms hand and crew served weapons. It is used by using troops, depots, and supply organizations.

### Reset Responsibility

Unit

### Reset Location

This system is not currently in reset.

**This system is not currently in reset.**

### Reset Type

**Reset Work (Field Level)** - Work performed to correct equipment faults that are performed at the ORG/DS level; performed by unit level soldiers, augmented by contractor as required.

### Reset Strategy

n/a

### Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.
- Reorder consumables IAW SC.

### **- Contact Information -**

877.4.PMSKOT (877.476.7568)  
[rock-pm-skot@conus.army.mil](mailto:rock-pm-skot@conus.army.mil)